

Move into the future with reliable measurements




Products for PCB Strain measurement

Simple Strain measurement of PCB



 Printed Circuit Assembly Stress Measuring Software
PCAS-100A

 Printed Circuit Assembly Stress Analysis Software
PCAS-200A






Measurement and analysis according to IPC/JEDEC-9704A can be performed easily. Strain measurement can be done easily by referring to strain gage bonding guidance and intuitive measuring instrument setting.



Analysis reports according to IPC/JEDEC-9704A can be created from measurement data recorded with Kyowa measurement instruments and its control software DCS in simple process.

Lineup

Models	Data Acquisition	Data Analysis	Creating Report	Available Channels	with PCD-400A
 PCAS-100A	○	○	○	16ch	—
 PCAS-200A	—	○	○	128ch	—
 PCAS-1000A	○	○	○	16ch	○

Sales Network



Americas Region

KYOWA AMERICAS Inc.
TEL: +1-248-348-0348
E-mail: sales@kyowa-americas.com
Website: <http://www.kyowa-ei.us/>

China

KYOWA ELECTRONIC(SHANGHAI)TRADING CO.,LTD.
TEL: +86-21-64477770
E-mail: support-cn@d1.kyowa-ei.co.jp
Website: <http://www.kyowa-ei.cn/>

Thailand

KYOWA DENGYO(THAILAND) CO.,LTD.
TEL: +66-2-117-3760
E-mail: sales-thailand@kyowa-ei.co.th
Website: <http://www.kyowa-ei.co.th/>

Other Countries or Regions

Please visit below URL.
Website: <http://www.kyowa-ei.com/>

Kyowa Electronic Instruments Co.,Ltd.

Overseas Department:
3-5-1, Chofugaoka, Chofu, Tokyo 182-8520 Japan
TEL; +81-42-489-7220 FAX: +81-42-488-1122
E-mail: kyowaoverseas.hp@d1.kyowa-ei.co.jp
Website: <http://www.kyowa-ei.com/>



Safety Precautions

Be sure to observe the safety precautions given in the instruction manual, in order to ensure correct and safe operation.

• Specifications are subject to change without notice for improvement.



JQA-0821
JQA-EM4824

Manufacturer's Representative